Item #: 6F

Date: 5/4/23

Spreader Bay Door Replacement

Rick Atkinson, Director, Equipment Maintenance

POT Regular Meeting

May 23, 2023



Action Requested



Request authorization in the amount of \$370,000 for a Spreader Bay Door replacement. The Port of Tacoma spreader bay has curtain style doors that are failing and need to be replaced.

- New doors \$315,000
- Labor for retrofitting \$55,000
- Total \$370,000

Background



The Port of Tacoma equipment maintenance team is needing to replace the defective curtain style doors to our spreader bay maintenance area with a high-speed fold up door designed for large openings.

- This is our primary repair area for the spreaders and where the technicians perform welding, painting, and electrical repairs.
- The current curtain doors only cover one side of the spreader bay and the bay has two major openings. Rain and wind gust into the bay and damages electrical components when the equipment is opened for repairs and painting is difficult in those conditions.

Background



- This set-up does not effectively keep the elements and cold temperature out which makes it difficult to preheat the metal when welding in the winter due to the area cannot be heated properly.
- The current curtain doors are difficult to close in the wind and present a safety issue.
- The new doors will seal off the area from the elements and allow for more efficient repairs getting the equipment back to the customer in a timely manner.

Spreader Bay Door Replacement - Current



Current Door

 In closed position, curtain is difficult to close. Does not effectively keep rain, wind, and cold temperature out.



Spreader Bay Door Replacement - Current



Second Opening of Spreader Bay

- This end does not have a door to keep the elements out.
- The proposal includes a second door to cover this opening.



Spreader Bay Door Replacement - Proposed



Proposed Roll Up Door

TECHNICAL DATA















MEGAPACK 200 an high speed fold up door designed for large openings, where it is necessary to make large logistics movements.



DOOR THICKNESS	300 mm	
	300 11111	
WINDOWS	1200 x 300 mm	
SEALS	Lateral PVC	
SPEED	0,2 - 0,3 m/s	
WIND RESISTANCE* DIFFERENTIAL PRESSURE	Classe EN 12424	
WIND SPEED DURING DOOR OPENING	< 20 m/s (72 km/h)	
SOUNDPROOFING STANDARD	15 dB Rw (ISO 717)	
WATER RESISTANCE	0,11 kPa (close door) Class 3, EN12426	
AIR PERMEABILITY	12m³ / (m²h) Class 3, EN 12426	
OPERATING TEMPERATURE OPERATING ENVIRONMENT	-10°C a +70°C	

^{*}The door, according to the directive 13241/ $\overline{\text{EC}}$, needs to be checked every six months.



Spreader Bay Door Replacement - Financial Impact



ltem	Budget Estimate	Expenditure to Date	Additional Anticipated Expenditures	Anticipated Future Expenditures
On-Call Design Consultant	\$26,000			\$26,000
Procurement	\$230,000			\$230,000
Construction	\$30,000			\$30,000
Other*	\$84,000			\$84,000
TOTAL	\$370,000			\$370,000

^{*}Other includes Washington State sales tax, contingency, permitting and miscellaneous costs

